Message

doylecks@comcast.net [doylecks@comcast.net] From:

3/11/2017 9:24:05 PM Sent:

To: Sean.F.Fitzgerald@uscg.mil; Beslow, Mike [beslow.mike@epa.gov]; DGREINKE@idem.IN.gov;

thomas.barnett@arcelormittal.com; kevin.lurtz@arcelormittal.com

Subject: Fwd: ArcelorMittal Indiana Harbor West - 3/8/17 Outfall Inspection, Sump Report, Photos

Attachments: IMG 0141.jpg; IMG 0143.jpg; FROM IHWPQ204@arcelormittal.com.pdf

Attached are the pictures for Saturday March 11th. Dave our picture taker has had a flat tire outside the facility so I will likely send the sump reports tomorrow.

Kevin Doyle

From: "Kevin Doyle" < Kevin.Doyle@arcelormittal.com >

To: doylecks@comcast.net

Sent: Wednesday, March 8, 2017 1:57:58 PM

Subject: FW: ArcelorMittal Indiana Harbor West - 3/8/17 Outfall Inspection, Sump Report, Photos

From: Lurtz, Kevin

Sent: Wednesday, March 08, 2017 1:56 PM To: Fitzgerald, Sean F MST1; Beslow, Mike

Cc: David Greinke (DGREINKE@idem.IN.gov); nream@idem.IN.gov; Doyle, Kevin; Barnett, Thomas R; Benoit, Simonne T

Subject: ArcelorMittal Indiana Harbor West - 3/8/17 Outfall Inspection, Sump Report, Photos

Kevin J. Lurtz | Environmental Engineer ArcelorMittal Indiana Harbor LLC | ArcelorMittal USA LLC.

MEU Environmental | 3001 Dickey Road, Sta. 001 East Chicago, IN 46312

T +219 399 3189 | F +219 399 3211 |M +219 552 4517 | www.arcelormittal.com

Please consider the environment before printing this email. ArcelorMittal encourages environmental awareness.